
















FSMA-Accessories

Description	Part number	Drawing
Crimping sleeve for Ø 2.0 mm cable	CRHS-3500-2000	
Crimping sleeve for Ø 2.5 mm cable	CRHS-3500-2500	
Crimping sleeve for Ø 2.8 mm cable	CRHS-3500-2800	
Crimping sleeve for Ø 3.0 mm cable	CRHS-3500-3000	
Crimping sleeve for Ø 3.5 mm cable	CRHS-3500-3500	
Dust cap for connector	FRSK-3015-00x0	
Dust cap for adaptor	SSK0-0610-00x0	
Dust cap, undetachable for ferrule 3,175 mm	USKK-3175-00x0	
Dust cap, metal, for adaptor, screwable	SSKM-FS56-1436	
Dust cap, metal, undetachable for connector, screwable	USKM-FS56-1436	

Description	Part number	Drawing
Boots for cable, 33 mm long for Ø 2.0 mm cable	KBKN-0033-20 XX	
Boots for cable, 33 mm long for Ø 2.5 mm cable	KBKN-0033-25 XX	
Boots for cable, 40 mm long for Ø 2.8 mm till 3.0 mm cable	KBKN-0040-30 XX	
Boots for cable, 40 mm long for Ø 3.5 mm cable	KBKN-0040-35 XX	
Boots for fiber, 25 mm long	KBKN-3525-09 XX	

Please replace XX with the code of desired colour.

XX = Black = 10 Red = 20 Yellow = 30 Green = 40
 = Blue = 50 Grey = 60 Orange = 70 White = 80