














ST-Accessories

Description	Part number	Drawing
Crimping sleeve for Ø 2.0 mm cable	CRHS-3500-2000	
Crimping sleeve for Ø 2.5 mm cable	CRHS-3500-2500	
Crimping sleeve for Ø 2.8 mm cable	CRHS-3500-2800	
Crimping sleeve for Ø 3.0 mm cable	CRHS-3500-3000	
Crimping sleeve for Ø 3.5 mm cable	CRHS-3500-3500	
Dust cap for connector	FRSK-2515-00x0	
Dust cap for adaptor	SSK0-0710-00x0	
Dust cap, undetachable for ferrule 2.5 mm	USKK-2500-00x0	

Description	Part number	Drawing
Boots for cable, 33 mm long for Ø 2.0 mm cable	KBKN-0033-20 XX	
Boots for cable, 33 mm long for Ø 2.5 mm cable	KBKN-0033-25 XX	
Boots for cable, 40 mm long for Ø 2.8 mm till 3.0 mm cable	KBKN-0040-30 XX	
Boots for cable, 40 mm long for Ø 3.5 mm cable	KBKN-0040-35 XX	
Boots for fiber, 25 mm long	KBKN-3525-09 XX	

Please replace XX with the code of desired colour.

XX = Black = 10 Red = 20 Yellow = 30 Green = 40
 Blue = 50 Grey = 60 Orange = 70 White = 80